

SPLICE FAILURE

The Almex Lab is equipped with everything necessary to test and diagnose the cause for a splice failure. Our testing staff are experienced splice experts who can provide the tests and final report to explain the cause of the failure to prevent costly re-occurrence.

FEATURES:

- Send your failed splice to us for an objective, unbiased, assessment
- Our experts can determine the root cause which can help to prevent additional splice problems .





Each splice failure test results in a comprehensive report being provided to the customer.





Shaw Almex Europe B.V. **3**1 646648648 Drachten, The Netherlands

Shaw Almex Industries 1 905 643 7750 Stoney Creek, Ontario

Shaw Almex Industries **** 1 705 746 5884 Parry Sound, Ontario

Shaw Almex Fusion, LLC. **1** 404 292 8600 Decatur, Georgia, USA

Shaw Almex Africa (Pty) Ltd. **C** 27 11 794 8262 South Africa

1.800.977.5423 www.almex.com sales@almex.com